

Fluctuations in readings when using the UV-Vis Calibration Kit - Tech Information

Fluctuations in readings in a UV-vis instrument are almost certainly due to a failing lamp.

A typical instrument which uses a xenon lamp is normally rated for only about 500 hours, while a deuterium can range from 1,000-3,000 hrs. However, they will sooner or later need to be replaced. If you are not sure of the hours on the lamp, I would start by replacing it to eliminate any fluctuations. If changing the lamp doesn't fix the problem, then you may need a service call.

Using the UV-Vis Calibration Kit will flag a problem such as this before erratic or poor data results from the bad lamp.

Click [HERE](#) for UV-Vis calibration kit ordering information and pictures.

Printed from the Chrom Resource Center

Copyright 2025, All Rights Apply

MicroSolv Technology Corporation

9158 Industrial Blvd. NE, Leland, NC 28451

Tel: (732) 380-8900

Fax: (910) 769-9435

Email: customers@mtc-usa.com

Website: www.mtc-usa.com